

4154 Traceable® Remote Alarm RH/Temp. Monitor (Upgraded Model)



RH Range	5.0 to 95.0%
RH Resolution	0.1% RH
RH Accuracy	±3% RH from 25-75%, ±5% otherwise
# RH Probes	1
Probe Temperature Range	0.0 to 60.0°C (32.0 to 140.0°F)
Probe Temperature Resolution	0.1°
Probe Temperature Accuracy	±0.5°C
# of Probes	1
LCD Digit Size	1/2 in
Dimensions	4-1/4"x3/4"x2-3/4"
Weight	4 ounces
A/C Plug (Y/N)	N
Traceable	Y
CE Marked	Y
Supplied With	battery, external humidity/temperature sensor, flip-open stand, wall mount, Traceable® Certificate