

**TRACEABLE<sup>®</sup>**  
**PRODUCTS**

Always Individually Calibrated,  
Certified and Traceable<sup>®</sup> to NIST

- 4088 Traceable<sup>®</sup> Hygrometer/Thermometer



<b>RH Range</b>	25 to 90% RH
<b>RH Accuracy</b>	±5% RH (40 to 80% RH) otherwise ±7% RH
<b>RH Resolution</b>	1% RH
<b># RH Probes</b>	1
<b>Probe Type</b>	Internal Sensor
<b>RH Probe External/Internal?</b>	Internal(Ambient)
<b>Temperature Range</b>	0 to 50°C (32.0 to 122.0°F)
<b>Internal Temperature Range</b>	0 to 50°C (32.0 to 122.0°F)
<b>Internal Temp Resolution</b>	1°
<b>RH Min/Max Memory (Y/N)</b>	Y
<b>Data Logging (Y/N)</b>	N
<b>Exportable Data (Y/N)</b>	N
<b>A/C Plug (Y/N)</b>	N
<b>Traceable</b>	Y
<b>Supplied With</b>	screws for wall mounting, plastic stand for bench use, ABS plastic case, battery, Traceable® Certificate



© Copyright 2015. All Rights Reserved by Control Company